



OPTIONAL

www.eclipse.aero

ECLIPSE
AEROSPACE

SERVICE BULLETIN

NUMBER: SB 500-34-002, REV E
MODEL: ECLIPSE EA500
SUBJECT: OPTIONAL INSTALLATION OF A THIRD ATTITUDE INDICATOR

1. PLANNING INFORMATION

A. Effectivity

Aircraft Model EA500 Serial Numbers 000001 through 000104, 000113 through 000115, 000120, and 000123 through 000124 are eligible to receive this option.

B. Reason

A third Attitude Indicator is required for Part 135 operations.

Revision E cancels this Service Bulletin

C. Description

This Service Bulletin has been canceled.

This SB Provides for the optional installation of a third Attitude Indicator. This third Attitude Indicator is required for Part 135 operations.

D. Relevant Publications

None

E. Compliance

None

F. Approval

This Service Bulletin is based on engineering data that is FAA-approved, and the modification herein complies with the applicable regulations.

G. Weight and Balance Change

None

H. Electrical Load Data Change

None

I. Software Accomplishment Summary

None

J. References

Not applicable

K. Publications Affected

None

3. ACCOMPLISHMENT INSTRUCTIONS

A. This Service Bulletin has been canceled.

4. RECORD OF COMPLIANCE

Not applicable



OPTIONAL

ECLIPSE
AEROSPACE

SERVICE BULLETIN

5. NOTIFYING ECLIPSE AVIATION

On completing this service bulletin, the operator/maintainer shall complete the attached Compliance Record and send it to Eclipse Aviation via regular mail, fax, or e-mail.

Mailing Address	Eclipse Aerospace Incorporated ATTN: Customer Care 2503 Clark Carr Loop SE Albuquerque, NM 87106
Fax	1-505-241-8802
E-mail	sbcompliance@eclipse.aero

