

SUBJECT: Antenna Diverter Strip Replacement

Aircraft Type: Eclipse 500

Effectivity: All

Applicability: CI 2728-410 GPS/XM/VHF ComDat® Antenna

## 1. SUMMARY:

This Service Information Letter announces the availability of a field service kit to replace damaged antenna diverter strips.

## 2. BACKGROUND

The lightning diverter strips installed on the CI 2728-410 ComDat® antenna can become damaged due to exposure to the environment. Replacement of the diverter strips has previously been accomplished by replacing the affected antenna.

## 3. ECLIPSE ACTION

EAI has approved a field service kit that allows for replacement of the diverter strip without having to replace the entire antenna.

## 4. SUGGESTED OPERATOR ACTION

If an operator notices damage to the diverter strip on either ComDat® antenna contact EAI to schedule replacement of the strip. If the affected antenna is serviceable, installation of the field kit to replace the diverter strip represents a significant cost savings versus replacement of the entire antenna.

## 5. Export Control

**These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. These commodities, technology or software are intended for use only in the End User's country. An export license from the U.S. Department of Commerce may be required before these products can be re-exported, transferred, transshipped on a non-continuous voyage, or otherwise disposed of in any other country, either in their original form or after being incorporated into an end item. Diversion of this end-item or its use contrary to any applicable U.S. government license or to U.S. law is prohibited.**

**INFORMATIONAL. This service letter is for informational purposes only.**

---