

TEMPORARY REVISION NO. 014
To EA500 POH and FAA-Approved Airplane Flight Manual
THROTTLE STOPS

This Temporary Revision affects the AFM Part Number 06-100106, Revision 04, dated December 13, 2007. DO NOT remove until directed to do so by a superseding Temporary or Regular revision, a Transmittal Letter, or a Service Bulletin. Record this TR insertion (or removal) on the Log of Temporary Revisions.

The following information is added to or supersedes the Normal Procedure Checklists listed below.

Insert in Section 4, between pages 12 & 13.

BEFORE TAKEOFF

Add the following NOTE to the end of this procedure:

NOTE

Never use excessive force against the Throttle Stops.

(TR Continues on Next Page)

FAA Approval: 	Date: June 12, 2008
---	---------------------

Issued: June 12, 2008

TR-014
1 of 2

Part No. 06-100106
Between 4-12 & 13

MISSED APPROACH/GO-AROUND

Replace Step 1 with the following:

1. Throttles MAX (Do Not Use Excessive Force against stops.)