

TEMPORARY REVISION NO. 01
To: Eclipse SE™ / Total Eclipse Plus™ / Eclipse 500 Plus™
Quick Reference Handbook

Effectivity Clarification

This Temporary Revision affects the QRH Part Number 06-123845, Revision "Original Issue", dated October 21, 2015. Remove this TR when Revision 02 is inserted. Record this TR insertion (or removal) on the Log of Temporary Revisions.

Insert this page behind LOTR-1.

06-123845-TR01

THIS PAGE INTENTIONALLY LEFT BLANK

REVISIONS

WARNING

It shall be the responsibility of the owner/operator to ensure that the latest revisions of publications referenced in this handbook are utilized during operation, servicing, and maintenance of the airplane.

The portion of text or an illustration that has been revised is denoted by a solid revision bar located adjacent to the area of change on the outside margin of the page.

For detailed information on how to obtain revision services applicable to this or other Eclipse Aerospace Service Publications, contact Eclipse Aerospace.

Eclipse Aerospace expressly reserves the right to supersede, cancel, and/or declare obsolete without prior notice any part, part number, kit or publication referenced in the *AFM/POH*.

EFFECTIVITY

This Quick Reference Handbook (QRH), part number 06-123845, shall be used on Eclipse aircraft according to the effectivity listed in the corresponding *AFM/POH* (part number 06-123844) Section 1.

If any conflicting information is found between the *AFM/POH* and this QRH, the *AFM/POH* shall take precedence.

THIS PAGE INTENTIONALLY LEFT BLANK