

## SERVICE BULLETIN

**NUMBER:** SB 500-11-001  
**MODEL:** Model 500  
**SUBJECT:** Placard Modification – Max Aft Baggage Weight

### 1. Planning Information

#### A. Effectivity

Model 500, Serial Number 000001

#### B. Reason

- (1) One placard in the aft baggage area, left cabin sidewall, had an error in the metric conversion of the maximum allowable baggage weight for that area.
- (2) The 260 lbs limit is correct, the conversion into kilograms should have been (118 KG) and not (120 KG).

#### C. Description

- (1) This Service Bulletin (SB) replaces the wrong placard (p/n 11-102927- x) with the correct placard (p/n 11-121485-x).
- (2) The new placard is in agreement with the placard depicted in the EA 500 Airplane Flight Manual p/n 06-100106 Rev 02 and later.

#### D. Compliance

- (1) Eclipse Aviation Corporation considers this to be an mandatory modification that *must* be accomplished as soon as possible but no later than 30 calendar days after issuance of this SB.

#### E. Approval

This Service Bulletin is based on engineering data that is FAA approved and the modification herein complies with the applicable regulations.

#### F. Weight and Balance Change

None.

#### G. Electrical Load Data Change

None.

#### H. Publications Affected

IPC will show only the new placard p/n 11-121485-x.

## SERVICE BULLETIN

### 2. Material Information

#### A. Materials

The following part is required for this modification:

Part Number	Description	Qty Required
11-121485-2002	PLACARD, AFT BAGGAGE MAXIMUM WEIGHT	one

### 3. Accomplishment Instructions

#### A. Procedure

- (1) Locate existing placard on the left side of the aft cabin, facing forward on the APC cover.
- (2) Remove existing placard p/n 11-102927
- (3) Insure surfaces are free of dirt and oil before application of the new placard
- (4) Apply new placard p/n 11-121485-2002 in the same location than the removed placard, .75 in. below the "INLET-APC COVER" placard and aligned with it.

**MAX BAGGAGE LOAD: 260 LBS (118 KG)**  
**DISTRIBUTE LOAD EVENLY OVER BAGGAGE FLOOR AREA**

New Placard p/n 11-121485-2002

#### B. Cost

Part and labor will be supplied by EAC at no cost to the customer.

### 4. Record of Compliance

- (1) Upon completion of this Service Bulletin, make an appropriate maintenance-record entry specifying the Service Bulletin number (including part number).

#### B. Notifying Eclipse Aviation

On completing this service bulletin, the operator/maintainer shall complete the attached *Compliance Record* and send it to Eclipse Aviation via regular mail, fax, or e-mail.

*Mailing Address:* Eclipse Aviation Corporation  
ATTN: Customer Care  
2503 Clark Carr Loop SE  
Albuquerque, NM 87106

*Fax:* 1-505-241-8802

*E-mail:* [customercare@EclipseAviation.com](mailto:customercare@EclipseAviation.com)

