

SUBJECT: Wing/Horizontal Stabilizer De-Ice Boot Repair
Aircraft Type: Eclipse 500 and 550
Effectivity: All Aircraft
Applicability: All Aircraft

1. SUMMARY

This SIL introduces the availability of repair kits for the wing and horizontal stabilizer de-ice boots.

2. BACKGROUND

EAI has received customer requests to develop repairs for the wing and horizontal stabilizer de-ice boots to prevent replacement of the boots for minor damage.

3. ECLIPSE ACTION

EAI has approved two repair kits for minor damage to the wing and horizontal stabilizer de-ice boots. In addition, EAI has published AMM Temporary Revision (TR) No. TR30-1, which provides instructions and limitations regarding the use of these repairs.

4. SUGGESTED OPERATOR ACTION

Two repair kits are available for the wing and horizontal stabilizer de-ice boots. The appropriate kit to use depends on the size of the damage. Operators with aircraft having a damaged wing or horizontal stabilizer de-ice boot should consult the noted TR to determine its repairability. Both repair kits are available from EAI.

De-ice boots with damage that exceeds the limitations noted in the TR must be replaced.

5. EXPORT CONTROL

These commodities, technology or software, were exported from the United States in accordance with the Export Administration Regulations. These commodities, technology or software are intended for use only in the End User's country. An export license from the U.S. Department of Commerce may be required before these products can be re-exported, transferred, transshipped on a non-continuous voyage, or otherwise disposed of in any other country, either in their original form or after being incorporated into an end item. Diversion of this end-item or its use contrary to any applicable U.S. government license or to U.S. law is prohibited.

INFORMATIONAL — This service letter is for informational purposes only.